
Model 123 126 up through 08.1985



## Visual inspection

Hydraulic fluid pump Fluid reservoir Level controller Pressure reservoir Spring struts Line connections

Check hoses and lines for chafing, dents, cracks, corrosion, and leaks (with engine running).

Note: To check for leaks that may only occur when the vehicle is loaded, check vehicle with the engine running and with vehicle rear loaded with approx. 150 kg (or 2 persons).